

CENTRAL POLLUTION CONTROL BOARD

Central Pollution Control Board, 'Parivesh Bhavan', East Arjun Nagar, Delhi - 110032



Water Laboratory (ANALYSIS REPORT)

Fresh Water Samples for Physico-Chemical Analysis Report

ULR No:

1. Report No. & Date of Issue : ,01/01/0001

2. Samples Registration No. & Date : WATER/FW/2324/SR00005,28/07/2023

3. Analysis Request Division/Organization : WQM-II

4. Sample Collected by : Dr. Pankaj Kumar ,Ms. Kusum

5. Sample Matrix : Fresh Water

6. Sampling Plan Preference

7. Date of Sample Receipt : 28/07/2023

8. Sample Analysis Period : 01/08/2023 02/08/2023

9. Sample Details

10. Report Status : Partial

11. Report Sent To : DH of WQM-II

Sr. No	Field Code	Date of Sample Collection	Parameter Name	Unit	Result Val
1	PC8	27/07/2023	рН		7.3
2	PC8	27/07/2023	Conductivity		1604
3	PC8	27/07/2023	COD		BDL
4	PC8	27/07/2023	TDS		
5	PC8	27/07/2023	Total Hardness		
6	PC8	27/07/2023	Chloride		

Remarks (if any):

Statement:

- 1. The results relate only to the samples tested.
- 2. The report shall not be reproduced except in full. without the written approval of the laboratory.

Analyst Supervisor & Reviewer Issued By (DH Water-Science Lab)

Doc: Issue No.: Revision No :	Issue Date:01/01/0001	Revision Date: 01/01/0001
-------------------------------	-----------------------	---------------------------

Date: 10 Aug 2023 This is a computer-generated Report. No signature is required.