

CENTRAL POLLUTION CONTROL BOARD

Central Pollution Control Board, 'Parivesh Bhavan', East Arjun Nagar, Delhi -

110032



Water Laboratory (ANALYSIS REPORT)

Fresh Water Samples for Physico-Chemical Analysis Report

ULR No:

1.	Report No. & Date of Issue	:	,01/01/0001
2.	Samples Registration No. & Date	:	WATER/FW/2324/SR00006,31/07/2023
3.	Analysis Request Division/Organization	:	WQM-II
4.	Sample Collected by	:	Ms. Manu Jindal,Ms Megha, SRF
5.	Sample Matrix	:	Fresh Water
6.	Sampling Plan Preference	:	
7.	Date of Sample Receipt	:	31/07/2023
8.	Sample Analysis Period	:	01/08/2023 02/08/2023
9.	Sample Details	:	
10.	Report Status	:	Partial
11.	Report Sent To	:	DH of WQM-II

Sr. No	Field Code	Date of Sample Collection	Parameter Name	Unit	Result Val
1	7	28/07/2023	рН		7.3
2	7	28/07/2023	Conductivity		4890
3	7	28/07/2023	COD		07
4	7	28/07/2023	TDS		
5	7	28/07/2023	Chloride		
6	7	28/07/2023	Total Hardness		
7	VR6	28/07/2023	рН		7.3
8	VR6	28/07/2023	Conductivity		3800
9	VR6	28/07/2023	COD		05
10	VR6	28/07/2023	TDS		
11	VR6	28/07/2023	Chloride		
12	VR6	28/07/2023	Total Hardness		

Remarks (if any) :

Statement :

1. The results relate only to the samples tested.

2. The report shall not be reproduced except in full. without the written approval of the laboratory.

Analyst

Supervisor & Reviewer

Issued By (DH Water-Science Lab)

Doc:	Issue No.:	Revision No :	Issue Date:01/01/0001	Revision Date: 01/01/0001	
------	------------	---------------	-----------------------	---------------------------	--

Date: 08 Aug 2023

This is a computer-generated Report. No signature is required.