

CENTRAL POLLUTION CONTROL BOARD

Central Pollution Control Board, 'Parivesh Bhavan', East Arjun Nagar, Delhi -

110032



Water Laboratory (ANALYSIS REPORT)

Fresh Water Samples for Physico-Chemical Analysis Report

ULR No:

1.	Report No. & Date of Issue	:	,01/01/0001
2.	Samples Registration No. & Date	:	WATER/FW/2324/SR00011,01/08/2023
3.	Analysis Request Division/Organization	:	WQM-II
4.	Sample Collected by	:	Mr. Rakesh Ahuja, Mr. Ravindra
5.	Sample Matrix	:	Fresh Water
6.	Sampling Plan Preference	:	
7.	Date of Sample Receipt	:	02/08/2023
8.	Sample Analysis Period	:	02/08/2023 03/08/2023
9.	Sample Details	:	STP Bijnor and Narora
10.	Report Status	:	Partial
11.	Report Sent To	:	DH of WQM-II

	Report Sent To				
Sr. No	Field Code	Date of Sample Collection	Parameter Name	Unit	Result Val
1	B8	31/07/2023	COD		BDL
2	B8	31/07/2023	Conductivity		312
3	B8	31/07/2023	рН		8.0
4	B8	31/07/2023	TDS		
5	B8	31/07/2023	Total Hardness		
6	B8	31/07/2023	Chloride		
7	B8	31/07/2023	Total Suspended Solids		
8	NN9	31/07/2023	COD		BDL
9	NN9	31/07/2023	Conductivity		567
10	NN9	31/07/2023	рН		7.4
11	NN9	31/07/2023	TDS		
12	NN9	31/07/2023	Total Hardness		
13	NN9	31/07/2023	Chloride		
14	NN9	31/07/2023	Total Suspended Solids		

Remarks (if any) :

Statement :

1. The results relate only to the samples tested.

2. The report shall not be reproduced except in full. without the written approval of the laboratory.

Analyst

Supervisor & Reviewer

Issued By (DH Water-Science Lab)

Doc:		Issue No.:	Revision No :	Issue Date:01/01/0001	Revision Date: 01/01/0001
------	--	------------	---------------	-----------------------	---------------------------