



CENTRAL POLLUTION CONTROL BOARD
Parivesh Bhawan, East Arjun Nagar, Delhi 110032



Water Laboratory
ANALYSIS REPORT

Requisition for Analysis of FreshWater Samples for Physico-Chemical Parameters

1. Report No. & Date of Issue : RP/00165,13/04/2023
2. Samples Registration No. & Date : Ce/2023/SR81,12/04/2023
3. Analysis Request Division/Organization : IPC-I
4. Sample Collected by : A. K. Tyagi,Syed ,Yagita,Namita ,Yashpal
5. Sample Matrix : Fresh Water
6. Sampling Plan :
7. Date of Sample Collection : 12/04/2023
8. Date of Sample Receipt : 12/04/2023
9. Date of Sample Analysis : 12/04/2023
10. Report Sent to (Division/Organization) :
11. Report Status : Final : Partial:

Sr. No	Sampling Coode	Lab Code	Parameter Name	Unit	Result Val
1	A1	WATER/FW23/00 30	Nitrite		1
2	A1	WATER/FW23/00 30	Phosphate		0.78
3	A1	WATER/FW23/00 30	Ammonia		2.9
4	A2	WATER/FW23/00 31	COD		BDL
5	A2	WATER/FW23/00 31	TDS		10

Remarks (if any) :

Statement :

1. The results relate only to the samples tested.
2. The report shall not be reproduced except in full. without the written approval of the laboratory.

Analyst

Supervisor & Reviewer

Issued By

Dinbandhu Gouda

Syed M Bilal

K. Ranganathan

Doc: CB/CL/QR/7.4/AL-1

Issue No.:1

Revision No :1

Issue Date:25/09/2022

Revision Date: 10/06/2022